o Date 9-12-86

o Revision - N/C

o System - Audio

a Assembly - Hand-Held Hicrophone

ATTACHMENT -

540210N

o Part Number - SE016101310-305 o Item Hame - Printed circuit board

o Reference Designation - None

Quantity per Assembly - 1

Function - Amplifies audio signal from microphone

o Failure Mode - EEE parts failure; loss of communication

 Failure Cause - EEE parts failure due to mechanical shock, vibration or crushing of the HHH housing

o Mission Phase - On-Orbit

o Failure Effect on End Item - Loss of communication

o Failure Effect on Interface - None

o Failure Effect on Mission - None

Failure Effect on Crew - None

o Failure Effect on Vehicle - None

 Failure Detection on Ground - Visual inspection and/or Audio Evaluation Test

 Failure Detection during Flight - Visual inspection and/or Voice Test

o Correcting Action - Use spare unit or VLHS

Criticality (Hardware/Functional) - 3/1R

Time Required to take Corrective Action - Estimated 5 minutes

o Time Available to take Corrective Action - Variable

o Remarks/Hazards - The HHM printed circuit board is conformal coated, and thermal and functional tests are performed on it after fabrication. The p.c.b. is solidly mounted in a very thin, lightweight case, which is vulnerable to crushing forces.

Page 5 10/2/86 REV. N/C